2004 Schedule of Programs

Quarterly Lab Survey Schedule

Quarterly Report Period	Mailout Target Date	Due Date
1 st Cycle	January 20, 2004	February 27, 2004
2 nd Cycle	April 19, 2004	May 21, 2004
3 rd Cycle	July 19, 2004	August 20, 2004
4 th Cycle	October 18, 2004	November 19, 2004

Associate Users Audit

Year	Mailout Target Date	Due Date
2004	June 7, 2004	July 9, 2004

Leak Test Schedule

Mailout Cycle	Mailout Target Date	Due Date
1 st Leak Test	January 20, 2004	February 27, 2004
2 nd Leak Test	July 19, 2004	August 20, 2004

X-Ray Producing Equipment Annual Inventory Audit

Year	Mailout Target Date	Due Date
2004	June 7, 2004	July 9, 2004

Sealed Source Inventory Audit

Audit Period	Mailout Target Date	Due Date
1 st Inventory Audit	February 9, 2004	March 12, 2004
2 nd Inventory Audit	August 9, 2004	September 10, 2004

Irradiator Survey

Survey Period	Mailout Target Date	Due Date
1 st Survey	January 20, 2004	February 20, 2004
2 nd Survey	July 12, 2004	August 13, 2004

LRPO Radioactive Waste Manifests

Survey Period	Mailout Target Date	Due Date
1 st Survey	February 9, 2004	March 12, 2004
2 nd Survey	August 9, 2004	September 10, 2004

Incineration Report

Audit Period	Mailout Target Date	Due Date
1 st Inventory Audit	February 16, 2004	March 19, 2004
2 nd Inventory Audit	May 10, 2004	June 11, 2004
3 rd Inventory Audit	August 9, 2004	September 10, 2004
4 th Inventory Audit	November 15, 2004	December 17, 2004

Unsealed Inventory

Inventory Period	Mailout Target Date	Due Date
1 st Inventory Audit	April 5, 2004	May 7, 2004
2 nd Inventory Audit	September 6, 2004	October 8, 2004